### HD Construction Change Orders

CHANGE ORDER NO. 1			
HD	Construct Rock Buttress as part of slope stability analysis.		
	Material, labor, equipment, Bales overhead & profit.		
	TOTAL INCREASE		\$ 31,460.00
CHANGE ORDER NO. 2			
HD	Deletion of fibermesh from concrete slabs	\$ (3,830.50)	
	Substitute aluminum feeders for copper feeders in elect panels	\$ (21,100.20)	
	Substitute alternate refrigerant piping	\$ (4,400.00)	
	Addition of floor sink to properly service kitchen scrapmaster	\$ 6,735.30	
	Addition of concrete culvert under north driveway to bus pkg	\$ 7,381.00	
	Delete dedication plaque, interior and exterior signage	\$ (7,605.00)	
	TOTAL DEDUCT		\$ (22,819.40)
CHANGE ORDER NO. 3			
HD	Elevator oil pump revision	\$ (1,617.62)	
	Revise gym and conference floor boxes	\$ 666.60	
	Revise focus room light fixture	\$ (39.82)	
	Add new water meter	\$ 2,360.62	
	TOTAL INCREASE		\$ 1,369.78
CHANGE ORDER NO. 4			
HD	Additional conduit required by COMO	\$ 3,695.45	
	PVC sleeves below walk at bus parking	\$ 3,941.17	
	TOTAL INCREASE		\$ 7,636.62
CHANGE ORDER NO. 5			
HD	Vestibule HVAC (FCU) - Option 1 return and restock of unit.	\$ 2,572.90	
	Provide 2 x 2 ceiling tile and grid in lieu of wood ceiling in vestibule.	\$ (4,913.70)	
	Provide additional steel for partition load and brick support ledge.	\$ 356.50	
	Add wiremold for thermostats in 144A, 150A, 134B, 101D, 105D.	\$ 1,253.49	
	TOTAL DECREASE		\$ (730.81)
CHANGE ORDER NO. 6			
HD	Provide power to scoreboard in the gym.	\$ 1,053.10	
	THIS WILL BE CREDITED TO THE DISTRICT.		\$ 1,053.10

CHANGE ORDER NO. 7

# HD Construction Change Orders

HD		Fire Lane Changes	\$	7,785.80	\$ 7,785.80
CHANGE O	RDER	Provide power to wall heaters not shown on electrical drawings.	\$	1,898.94	\$ 1,898.94
CHANGE O	RDER	Restripe bus lot per owner request.	\$	3,146.00	\$ 3,146.00
CHANGE O	RDER	Intercom speaker revisions.	\$	2,211.62	\$ 2,211.62
CHANGE O	RDER	Remobilization of Bloomsdale to construct sidewalk per owners request.	\$	8,800.00	\$ 8,800.00
CHANGE OF THE		Add polished concrete in area D.	\$	14,230.30	\$ 14,230.30
CHANGE ORDER N	NO. 8	Add steel guardrail in kitchen (behind equipment). Re-stripe bus parking lot per owner request. Re-mobilization costs to accelerate construction of entry sidewalk. Intercom speaker revisions. Add polished concrete floor slab in Area D. Provide power to wall heaters (near door). Furnish and install 6" wall resilient base (in lieu of 4") at Area D. Insulate existing above ceiling pvc piping in Area D with fire rated wrap. Deduct for elimination of Phase 2 sidewalks.	\$ \$ \$ \$ \$ \$ \$ \$	3,366.00 3,146.00 8,800.00 2,211.62 14,230.30 1,898.94 3,091.00 2,520.49 (7,920.00)	

# HD Construction Change Orders

Add new plumbing for sink in Room 113D (Mrs. Pace's room).	\$ 932.46	
Grout (for structural) non load bearing wall cells in existing Area D.	\$ 175.12	
Phase 2 parking lot re-striping, additional striping and signage.	\$ 2,930.62	
Tie-in fire alarm per Fire Marshal request.	\$ 1,061.95	
Furnish and install can lights in elevator lobby.	\$ 1,096.70	
Deduct for mow strip.	\$ (9,361.77)	

\$ 28,179.43

## CHANGE ORDER No. 9

HD

Phase One Playground Asphalt Credit \$ (12,500.00)

\$ (12,500.00)

\$ 71,721.38

# OBE Construction Change Orders

	CHANGE ORDER NO. 1					
	OBE	Change food service subcontractor to Ford Restaurant Supply	\$	1,450.00		
		City requests: add door signs	\$	404.00		
		Delete AWI certification paperwork	\$	(3,500.00)		
		Revisions to lift station retention chambers as City requested	\$	5,540.00		
		Deduct for interior door signage and exterior bldg letters	\$	(15,182.00)		
		TOTAL DECREASE			\$	(11,288.00)
(	CHANGE ORDER NO. 2					
	OBE	Revise location of fire dept connection as req by Fire Marshal	\$	5,424.00		
		Mass rock removal	\$	90,365.85		
		TOTAL INCREASE	•		\$	95,789.85
						,
	CHANGE ORDER NO. 3					
	OBE	Sewer line connection to main on Nichols Road	\$	(7,700.00)		
		Change floor height (Revised \$1 - 6/11/14)	\$	48,366.00		
		TOTAL INCREASE			\$	40,666.00
	CHANGE ORDER NO. 4					
		Revising electrical floor boxes in gym and adding power for				
	OBE	motorized roller shades and microphone outlet.	\$	4,747.89		
	052	TOTAL INCREASE	Y	1,7 17103	\$	4,747.89
		TO THE INVENEZ BE			۲	1,7 17103
	CHANGE ORDER NO. 5					
	OBE	Change tempered glass to laminated, focus room door.	\$	18.79		
		Focus room electrical requirements.	\$	(187.50)		
		TOTAL DECREASE			\$	(168.71)
	CHANGE ORDER NO. 6					
	OBE	Vegetable oil provided at elevator sump pump	Ċ	(871.56)		
	ODE	Additional electrical revisions in various rooms	\$ \$	2,495.37		
		TOTAL INCREASE	Ą	2,433.37	\$	1,623.81
		TOTAL INCIDENSE			ڔ	1,023.01

# OBE Construction Change Orders

OBE   Provide block heaters at bus area   S   29,472.42   Deduct power at two playground storage buildings   S   (4,357.76)   Revise responsibility matrix for data systems from contractor to owner   TOTAL INCREASE   S   6,786.82    CHANGE ORDER NO. 8	CHANGE ORDER NO. 7					
Revise responsibility matrix for data systems from contractor to owner TOTAL INCREASE \$ (18,327.84) \$ 6,786.82  CHANGE ORDER NO. 8  OBE Added letters to monument sign \$ 1,945.26 \$ 761.28 \$ 761.28 \$ 761.28 \$ 2,706.54  CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units \$ 1,607.46 \$ 4,000.000 \$ 701.200 \$ 321.12 \$ 4,000.000 \$ 4,0	OBE	Provide block heaters at bus area	\$	29,472.42		
to owner TOTAL INCREASE  CHANGE ORDER NO. 8  OBE Added letters to monument sign Modifications to elevator hoistway beam TOTAL INCREASE  CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units Added electrical power for water heater Switch recessed light fixture to surface mounted RFI 106 Added cable tray per RFI 114 Additional steel supports at Gym ductwork Additional steel supports at Gym ductwork Additional thermostats TOTAL INCREASE  CHANGE ORDER NO. 10  CHANGE ORDER NO. 10  CHANGE ORDER NO. 10  CHANGE ORDER NO. 10  CHANGE ORDER NO. 11  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots TOTAL DECREASE  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lots TOTAL DECREASE  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot  S 3,645.38  (13,001.98)		Deduct power at two playground storage buildings	\$	(4,357.76)		
CHANGE ORDER NO. 8		Revise responsibility matrix for data systems from contractor				
CHANGE ORDER NO. 8  OBE Added letters to monument sign \$ 1,945.26		to owner	\$	(18,327.84)		
OBE Modifications to elevator hoistway beam TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 2,706.54  CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units \$ 1,607.46 Added electrical power for water heater \$ 6,135.95 Switch recessed light fixture to surface mounted RFI 106 \$ 321.12 Added electrical power to smoke curtain per RFI 94 \$ 3,341.20 Added cable tray per RFI 114 \$ 2,687.96 Additional steel supports at Gym ductwork \$ 1,011.94 Additional thermostats \$ 3,883.62 TOTAL INCREASE \$ 18,989.25  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots \$ 3,464.63 Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions \$ 10,033.39 TOTAL DECREASE \$ (13,001.98)  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38 \$ (13,001.98)		TOTAL INCREASE			\$	6,786.82
OBE Modifications to elevator hoistway beam TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 761.28 TOTAL INCREASE \$ 2,706.54  CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units \$ 1,607.46 Added electrical power for water heater \$ 6,135.95 Switch recessed light fixture to surface mounted RFI 106 \$ 321.12 Added electrical power to smoke curtain per RFI 94 \$ 3,341.20 Added cable tray per RFI 114 \$ 2,687.96 Additional steel supports at Gym ductwork \$ 1,011.94 Additional thermostats \$ 3,883.62 TOTAL INCREASE \$ 18,989.25  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots \$ 3,464.63 Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions \$ 10,033.39 TOTAL DECREASE \$ (13,001.98)  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38 \$ (13,001.98)						
Modifications to elevator hoistway beam TOTAL INCREASE \$ 2,706.54  CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units \$ 1,607.46	CHANGE ORDER NO. 8					
CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units \$ 1,607.46 Added electrical power for water heater \$ 6,135.95 Switch recessed light fixture to surface mounted RFI 106 \$ 321.12 Added electrical power to smoke curtain per RFI 94 \$ 3,341.20 Added cable tray per RFI 114 \$ 2,687.96 Additional steel supports at Gym ductwork \$ 1,011.94 Additional thermostats \$ 3,883.62 TOTAL INCREASE \$ 18,989.25  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring \$ (19,000.00) Unsuitable soil conditions under parking lots \$ 3,464.63 Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions \$ 10,033.39 TOTAL DECREASE \$ (13,001.98)	OBE	Added letters to monument sign	\$	1,945.26		
CHANGE ORDER NO. 9  OBE Added electrical power for fan coil units \$ 1,607.46   Added electrical power for water heater \$ 6,135.95   Switch recessed light fixture to surface mounted RFI 106 \$ 321.12   Added electrical power to smoke curtain per RFI 94 \$ 3,341.20   Added cable tray per RFI 114 \$ 2,687.96   Additional steel supports at Gym ductwork \$ 1,011.94   Additional thermostats \$ 3,883.62   TOTAL INCREASE \$ 18,989.25  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring \$ (19,000.00)   Unsuitable soil conditions under parking lots \$ 3,464.63   Topsoil revisions per owner \$ (7,500.00)   Structural steel angles at operable partitions \$ 10,033.39   TOTAL DECREASE \$ (13,001.98)		Modifications to elevator hoistway beam	\$	761.28		
OBE Added electrical power for fan coil units \$ 1,607.46   Added electrical power for water heater \$ 6,135.95   Switch recessed light fixture to surface mounted RFI 106 \$ 321.12   Added electrical power to smoke curtain per RFI 94 \$ 3,341.20   Added cable tray per RFI 114 \$ 2,687.96   Additional steel supports at Gym ductwork \$ 1,011.94   Additional thermostats \$ 3,883.62   TOTAL INCREASE \$ 18,989.25    CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring \$ (19,000.00)   Unsuitable soil conditions under parking lots \$ 3,464.63   Topsoil revisions per owner \$ (7,500.00)   Structural steel angles at operable partitions \$ 10,033.39   TOTAL DECREASE \$ (13,001.98)    CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38		TOTAL INCREASE			\$	2,706.54
OBE Added electrical power for fan coil units \$ 1,607.46   Added electrical power for water heater \$ 6,135.95   Switch recessed light fixture to surface mounted RFI 106 \$ 321.12   Added electrical power to smoke curtain per RFI 94 \$ 3,341.20   Added cable tray per RFI 114 \$ 2,687.96   Additional steel supports at Gym ductwork \$ 1,011.94   Additional thermostats \$ 3,883.62   TOTAL INCREASE \$ 18,989.25    CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring \$ (19,000.00)   Unsuitable soil conditions under parking lots \$ 3,464.63   Topsoil revisions per owner \$ (7,500.00)   Structural steel angles at operable partitions \$ 10,033.39   TOTAL DECREASE \$ (13,001.98)    CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38						
Added electrical power for water heater Switch recessed light fixture to surface mounted RFI 106 Added electrical power to smoke curtain per RFI 94 Added cable tray per RFI 114 Additional steel supports at Gym ductwork Additional thermostats TOTAL INCREASE  Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots Total steel angles at operable partitions TOTAL DECREASE  CHANGE ORDER NO. 11 OBE Unsuitable soil conditions under south parking lot \$ 3,645.38						
Switch recessed light fixture to surface mounted RFI 106 \$ 321.12   Added electrical power to smoke curtain per RFI 94 \$ 3,341.20   Added cable tray per RFI 114 \$ 2,687.96   Additional steel supports at Gym ductwork \$ 1,011.94   Additional thermostats \$ 3,883.62   TOTAL INCREASE \$ 18,989.25  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring \$ (19,000.00)   Unsuitable soil conditions under parking lots \$ 3,464.63   Topsoil revisions per owner \$ (7,500.00)   Structural steel angles at operable partitions \$ 10,033.39   TOTAL DECREASE \$ (13,001.98)  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38	OBE	·				
Added electrical power to smoke curtain per RFI 94 \$ 3,341.20 Added cable tray per RFI 114 \$ 2,687.96 Additional steel supports at Gym ductwork \$ 1,011.94 Additional thermostats \$ 3,883.62 TOTAL INCREASE \$ 18,989.25  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring \$ (19,000.00) Unsuitable soil conditions under parking lots \$ 3,464.63 Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions \$ 10,033.39 TOTAL DECREASE \$ (13,001.98)  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38		Added electrical power for water heater		6,135.95		
Additional steel supports at Gym ductwork Additional thermostats TOTAL INCREASE   CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots Topsoil revisions per owner Structural steel angles at operable partitions TOTAL DECREASE  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 1,011.94		Switch recessed light fixture to surface mounted RFI 106		321.12		
Additional steel supports at Gym ductwork Additional thermostats TOTAL INCREASE TOTAL INCREASE  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots Topsoil revisions per owner Structural steel angles at operable partitions TOTAL DECREASE  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 1,011.94 \$ 1,011		Added electrical power to smoke curtain per RFI 94	\$	3,341.20		
Additional thermostats TOTAL INCREASE  CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots Topsoil revisions per owner Structural steel angles at operable partitions TOTAL DECREASE  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,883.62 \$ 18,989.25 \$ (19,000.00) \$ 3,464.63 \$ 7,500.00) \$ 10,033.39 \$ (13,001.98)		Added cable tray per RFI 114		2,687.96		
CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring (19,000.00) Unsuitable soil conditions under parking lots (17,500.00) Structural steel angles at operable partitions (10,033.39) TOTAL DECREASE (13,001.98)  CHANGE ORDER NO. 11 OBE Unsuitable soil conditions under south parking lot (3,645.38)				1,011.94		
CHANGE ORDER NO. 10  OBE Revised dyed and polished concrete flooring Unsuitable soil conditions under parking lots Topsoil revisions per owner Structural steel angles at operable partitions TOTAL DECREASE  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 10,033.39 \$ (13,001.98)		Additional thermostats	\$	3,883.62		
OBE Revised dyed and polished concrete flooring \$ (19,000.00) Unsuitable soil conditions under parking lots \$ 3,464.63 Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions TOTAL DECREASE \$ 10,033.39  **CHANGE ORDER NO. 11 OBE Unsuitable soil conditions under south parking lot \$ 3,645.38		TOTAL INCREASE			\$	18,989.25
OBE Revised dyed and polished concrete flooring \$ (19,000.00) Unsuitable soil conditions under parking lots \$ 3,464.63 Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions TOTAL DECREASE \$ 10,033.39  **CHANGE ORDER NO. 11 OBE Unsuitable soil conditions under south parking lot \$ 3,645.38	CHANGE ORDER NO. 1	0				
Unsuitable soil conditions under parking lots Topsoil revisions per owner Structural steel angles at operable partitions TOTAL DECREASE  CHANGE ORDER NO. 11 OBE Unsuitable soil conditions under south parking lot  \$ 3,464.63 (7,500.00) \$ 10,033.39 \$ (13,001.98)			ς	(19 000 00)		
Topsoil revisions per owner \$ (7,500.00) Structural steel angles at operable partitions TOTAL DECREASE \$ 10,033.39  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38	OBL					
Structural steel angles at operable partitions \$ 10,033.39						
TOTAL DECREASE \$ (13,001.98)  CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38						
CHANGE ORDER NO. 11  OBE Unsuitable soil conditions under south parking lot \$ 3,645.38			Y	10,033.33	Ś	(13.001.98)
OBE Unsuitable soil conditions under south parking lot \$ 3,645.38					τ	(==,===,=,
,	CHANGE ORDER NO. 1	1				
	OBE	Unsuitable soil conditions under south parking lot	\$	3,645.38		
Add shutoff valves at roof hydrants \$ 359.52		Add shutoff valves at roof hydrants	\$	359.52		

# OBE Construction Change Orders

	Add changing out one bent basketball mast w/straight one TOTAL INCREASE	\$ 4,407.33	\$	8,412.23
			·	,
CHANGE ORDER NO. 1	2			
OBE	Add kitchen railing .	\$ 1,979.50		
	Add sidewalk on south area C.	\$ 1,736.08		
	Add curb striping.	\$ 374.50		
	Dedicated power at HVAC controls.	\$ 236.81		
	Emergency lighting.	\$ 308.97		
	Receiving/kitchen intercom.	\$ 3,986.17		
			\$	8,622.03
	_			
CHANGE ORDER NO. 1	3			
OBE	Change kiln 30 amp breaker to 50 amp	\$ 1,460.29		
	Deduct for changing Dyson hand dryers to Blue Storm	\$ (10,000.00)		
	Deduct for allowances not used.	\$ (26,601.39)		
			\$	(35,141.10)

\$ 128,744.63

CHANGE ORDER NO. 1

HS Add Security Camera \$ 1,458.17

BALANCE \$ 1,458.17