

Safety Report-Camdenton R-III School District

September 9, 2015

Pursuant to Policy EB.C.1B: The district has a designated individual for implementing bullying-prevention programs.

<<http://policy.msbanet.org/camdenton/showpolicy.php?file=EB-C.1B>>

Pursuant to Policy EBAB-C.1B: The maintenance department coordinates the periodic testing of drinking water, by an approved testing lab, with the appropriate civil authorities.

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=EBAB-C.1B>>

Pursuant to Policy EBBA-C.CAM: The superintendent or designee (Neal) continuously reviews job descriptions and district activities to improve safety in the district

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=EBBA-C.CAM>>

Pursuant to Policy EBCA-C.1B: October 28, 2015, from 11a- 1p, Camdenton R-III will host the Camden County Safe Schools Committee in the board room. Officer Chris Williams will discuss any proposed changes to the district emergency response, hazardous materials response, or Use of School Resources plans with the committee at that time, no changes are expected this year.

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=EBCA-C.1B>>

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=EBCA-C.1B>>

Pursuant to Policy EBCA –C.1B: An agenda item is included on the District Fall Safety Meeting to discuss the classified nature of emergency response plans regarding intruders, threats, etc.

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=EBCA-C.1B>>

Pursuant to Policy EBC-C.CAM: Emergency drill dates have been established at the building level. Completion and description of all drills will be noted on a district provided form and checked by the central office each semester.

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=EBC-C.CAM>>

Pursuant to Policy ECA-C.CAM: Safety walk-throughs continue throughout the district. A report of the results thus far is appended to this document. A web-based form has been created for se by building principals, maintenance personnel, and district safety personnel to report safety hazards observed at any time.

Pasted from <<http://policy.msbanet.org/camdenton/showpolicy.php?file=ECA-C.CAM>>

Pursuant to Policy ECA-AP1.1B: Asbestos tests and notices are made and submitted as required by the maintenance department.

Pasted from <<http://policy.msbanet.org/camdenton/showproc.php?file=ECA-AP1.1B>>



Camdenton Fire Department

Physical Address: 35 College Ave

Mailing Address: 437 W US Hwy 54, Camdenton, MO 65020

Business (573) 346-6260 Fax (573) 346-6262

INSPECTION REPORT

Name of Business: Agricultural building Date: 8/13/15

Address: _____

Notes: Exit sign and emergency lighting in both classes don't work.
Storage too close to ceiling in office closet. Exit sign on south wall doesn't work.
Blocked access to electrical panels in mechanical room. Open electrical box,
Extension chord in green house.

Multiple horizontal lines for additional notes, with a large 'DRAFT' watermark diagonally across the page.

This fire prevention inspection was made for the purpose of promoting life safety and correcting conditions which may tend to cause or contribute to a fire situation. Any classifications marked NO shall be corrected in order to bring the safety conditions up to minimum standards as prescribed by the appropriate codes.

[Signature]
Owner/Agent Signature

[Signature] 309
Inspector Signature



Camdenton Fire Department

Physical Address: 35 College Ave

Mailing Address: 437 W US Hwy 54, Camdenton, MO 65020

Business (573) 346-6260 Fax (573) 346-6262

INSPECTION REPORT

Name of Business: Dogwood Elementary Date: 8/12/15

Address: 158 Minor Street

Notes: Obstruction in hallway by main doors. Access to panel in 60a. Multiplex adapter in 56.
Multiplex outlet in 58. Emergency lighting over gym men's bathroom. Extension chords in 76.
Multiplex adapter, extension chords in 74. Smoke detector, storage too high in 80A.
Blocked access to electrical panel 81s. Extension chords in 49. Extension chord in 48.
Emergency lighting outside 48. Multiplex outlet, extension chords in 46.
Multiplex outlet, extension chord in 47. Extension chord in 45. Storage height, smoke detectors in 43A
Extension chords in 43. Extension chords in 42. Multiplex outlet in 39. Access to panel in 29S.
Powers trip plugged into extension chord in 30. Extension chords in 32. Extension chords in 34.
Extension chord in 38. Extension chord in 67. Doors to courtyard need signs at eye level on the
Doors themselves that say not an exit. Exit sign in small cafeteria needs to be removed.
Emergency lighting doesn't work/obstructed outside 14. Smoke detector in closet, multiplex outlet
And extension chord in room 12. Exit sign outside 14a doesn't work. Extension chord in 14A.
Extension chord in lunchroom 1-s1. Smoke detector in closet in 17. Smoke detector in closet in 19.
Multiplex outlet, smoke detector in closet in 18. Smoke detector in closet in 21.
Smoke detector in closet, bad end on cart chord in 20. Smoke detector in closet in 22.
Smoke detector in closet, extension chord in 23. Smoke detector in closet in 24.
Extension chord to microwave in sheriffs office. All but the south east Exit sign in cafeteria 1.
Exit sign outside cafeteria 1. Smoke detector in closet 26b. Panel access in closet south east.
Extension chord in Mrs young. Storage in guided reading library. Extension chord in 28a.
Extension chord by restroom 28r. Extension chord to water dispenser.

This fire prevention inspection was made for the purpose of promoting life safety and correcting conditions which may tend to cause or contribute to a fire situation. Any classifications marked NO shall be corrected in order to bring the safety conditions up to minimum standards as prescribed by the appropriate codes.

Owner/Agent Signature

Inspector Signature



Camdenton Fire Department

Physical Address: 35 College Ave

Mailing Address: 437 W US Hwy 54, Camdenton, MO 65020

Business (573) 346-6260 Fax (573) 346-6262

INSPECTION REPORT

Name of Business: Hawthorn Elementary Date: 7/30/15

Address: 296 Minor St

Notes: Exit sign loading dock door. No key to 89a. Exit sign boys locker room doesn't work.
Exit sign southeast corner gym. Extension chords in 137-0. Emergency lighting outside 139.
Multiplex outlet in 141. Blocked panel in capstone computer lab. Extension chord in 144.
Exit sign "f" door capstone. Emergency lighting 143s. Multiplex in 1380.
Emergency light needs battery in capstone hallway. Exit sign outside of 134.
Flag pole holder outside 135. Both exit signs at main entrance. Extension chords in 94.
Extension chord in 97. Smoke detector, and storage too high in 99s. Extension chord in 100 and
In office. Batter in exit sign outside 99. Extension chord in 104. Extension chords in 111.
Extension chord in 112. Flag holders outside of rooms need removed. Storage too close to
Ceiling in 113. Extension chords in 116. Multiplex in 120. Extension chord in 121.
Smoke detector, storage too close in 4th grade storage. Emergency lighting in 122.
Emergency lighting outside room 122. Smoke detector in 3rd grade storage.
Extension chord in 126. Extension chord in 129. Extension chord in 130.
Emergency Light outside 132. Storage too high, smoke detector, extension chord in 96s.

This fire prevention inspection was made for the purpose of promoting life safety and correcting conditions which may tend to cause or contribute to a fire situation. Any classifications marked NO shall be corrected in order to bring the safety conditions up to minimum standards as prescribed by the appropriate codes.

Owner/Agent Signature

Inspector Signature



Camdenton Fire Department

Physical Address: 35 College Ave

Mailing Address: 437 W US Hwy 54, Camdenton, MO 65020

Business (573) 346-6260 Fax (573) 346-6262


INSPECTION REPORT


Name of Business: High School Date: 8/14/15

Address: _____

Notes: No key to get in secured entrance. Sprinkler head in work room. Storage too high in closets
By mailboxes. File cabinets in hallway in nurses office. Sprinkler head in main office.
Mats in common room. Storage too high choir room office. Storage too close to sprinkler heads in
Choir rooms. Storage too high in robe storage room. Multi plex adapter in band directors office.
Restricted access to roof access in stage shop. Rear exit from stage dead battery. Fire extinguisher
In fire cabinet rear stage needs serviced. Emergency lighting in left side of auditorium exit hallway.
Low battery in left rear auditorium emergency light. Low battery in light booth catwalk stairwell.
Open block in electrical panel in concession stand. Both Emergency lighting need battery in weight
Room. Emergency lighting in football locker room by office. Exit signs and emergency lighting need
Batteries in film room. Emergency lighting outside of girls athletic room. Blocked access to roof
Access and electrical panels in right upper gym storage. Extension chord in kitchen. Storage too
High in dry room storage. Battery low outside kitchen locker room. Blocked access to sprinkler
Controls. Extension chord in c114. Storage too high in c103. Extension chord in c122.
Power strip into power strip a102. Storage too high in a103. Rear door B103 jammed won't open
Storage across from B100 storage to close to ceiling closet B103 storage to close to ceiling
Storage to close to ceiling A120, extension cord C208, storage to close to ceiling C205,
Exit sign hallway outside A200 needs battery, multi adapter A206. Storage to close to ceiling A206
Storage to high A208, storeroom in B210 storage to close to ceiling B207 storage to close to ceiling
b205 storage to close to ceiling, exit sign rear of broadcast studio, D204 storage to close to ceiling

This fire prevention inspection was made for the purpose of promoting life safety and correcting conditions which may tend to cause or contribute to a fire situation. Any classifications marked NO shall be corrected in order to bring the safety conditions up to minimum standards as prescribed by the appropriate codes.


Owner/Agent Signature


Inspector Signature



Camdenton Fire Department

Physical Address: 35 College Ave

Mailing Address: 437 W US Hwy 54, Camdenton, MO 65020

Business (573) 346-6260 Fax (573) 346-6262

INSPECTION REPORT

Name of Business: Horizons Date: 8/12/15

Address: 172 W Highway 54

Notes: No address in front of building. Room number for fire extinguisher needs serviced.

Remove stored items from furnace room. Extension cord room 11. Multiplex outlet room 6.

Multiplex outlet by Secretary desk.

Multiple horizontal lines for additional notes, with a large 'DRAFT' watermark overlaid diagonally across the page.

This fire prevention inspection was made for the purpose of promoting life safety and correcting conditions which may tend to cause or contribute to a fire situation. Any classifications marked NO shall be corrected in order to bring the safety conditions up to minimum standards as prescribed by the appropriate codes.

Owner/Agent Signature

Inspector Signature



Camdenton Fire Department

Physical Address: 35 College Ave

Mailing Address: 437 W US Hwy 54, Camdenton, MO 65020

Business (573) 346-6260 Fax (573) 346-6262

INSPECTION REPORT

Name of Business: LCTC Date: 8/13/15

Address: 269 DARE

Notes: Extension chord in office. Multiplex outlet in 106. Smoke detector, storage too high in 108c.
Storage too high, smoke detector in 114. Extension chord in 116 storeroom.
Smoke detectors, storage too high both closets in 113. No ext sign on door in 113.
Extension chord, smoke detector in storage room in 109b. Storage too close to ceiling, extension
Chords in 103 & 101. Exit sign at main door dead. No key to closet by 120.
Emergency light needs fixed in 120 shop exit. Exit sign broken 131a. Emergency light into shop 120.
Flammable paint product in a fire closet in 137c. 1 fire extinguisher needed by 157 exit.
No Emergency lighting in addition hallway. Exit sign adult marine side needs battery.
Emergency light in men's and women's restroom in marine. No key to elevator control room.
Co extinguisher needs serviced or removed in metal fab. No power to emergency lighting and fire doc
No emergency lighting in metal fab. Co fire extinguisher needs service or removed in 136.
Use of storage area as class room. Emergency lighting in graphic tech lab. Emergency light needs
Battery in 132.

This fire prevention inspection was made for the purpose of promoting life safety and correcting conditions which may tend to cause or contribute to a fire situation. Any classifications marked NO shall be corrected in order to bring the safety conditions up to minimum standards as prescribed by the appropriate codes.

Owner/Agent Signature

Inspector Signature

Timestamp User r To which building

wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school
wkurtz | Middle school

8/12/2015 9:42:43 wkurtz | Dogwood
8/12/2015 9:43:33 wkurtz | Dogwood
8/12/2015 9:51:01 wkurtz | Dogwood
8/12/2015 9:51:27 wkurtz | Dogwood
8/12/2015 9:54:40 wkurtz | Dogwood
8/12/2015 9:59:08 wkurtz | Dogwood
wkurtz | Dogwood
wkurtz | Dogwood
wkurtz | Dogwood
wkurtz | Dogwood
wkurtz | Dogwood
wkurtz | Dogwood

wkurtz | Hawthorn
wkurtz | Hawthorn
wkurtz | Hawthorn
wkurtz | Hawthorn
wkurtz | Hawthorn
wkurtz | Hawthorn

wkurtz| Hawthorn
8/12/2015 wkurtz| hawthorn
8/12/2015 wkurtz| horizons
8/12/2015 wkurtz| horizons
8/12/2015 wkurtz| horizons
8/12/2015 wkurtz| horizons
8/12/2015 wkurtz| horizons
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc
8/13/2015 wkurtz| lctc

DRAFT

Room number or other description of location.

Office kitchen	216
	301
	305
	312
	313
	319
Outside rm 311	
Hallway outside 317-320	
Second floor by elevator.	210
	209
	234
	235
	241
Garage	
Interventions	
Hallway outside 233	226
	214
	228
	109
Outside321	
Kitchen by dock	
All but 4 room in the building	
Most classrooms are using extension cords or multipoutlet adapters, not allowed.	
80a,43a, every storage closet	
81s	
all but 8 rooms in the building, electric scent is a fire hazard, passive scent is against allergy policy.	
Outside 48	
	47
Courtyard etc doors need eyelevel signs "not an exit" on each door	
Exit sign in little cafeteria needs removed or directionality corrected.	
Hallway outside 14	
12a	
Cafeteria	
Gym	
Capstone hallway emer light battery, exit sign near dock, 8th grade locker room exit sign, exit sign SE corner of gym, emergency light outside 139, exit sign "f" door capstone rooms, 143 needs emergency lighting, both exit signs at main entrance, exit sign by rm 99, emergency lighting needed in 122 and outside rm 122 needs service, emergency lighting outside 132, ,	
Capstone computer lab.	
Lunch hallway,	
Key to 89a is not on fire keys stored in BOX.	
Old flagholders mounted by each classroom need to be removed.	
Most storage closets have items too close to the ceiling. 18" distance required please.	

Closets need smoke detectors installed

Many classrooms are using extension cords as permanent electrical supply. please remove

Address needs to be displayed on road side of building
room number for fire extinguisher needs serviced

remove stored items from furnace room

Multiplex outlet in rm 6 and sec desk need to be replaced with surge protector
extension cords cannot be used as a permanent fixture, room 11

multiple rooms and offices are using extension cords as a permanent electric supply. please use a power strip
or request an additional outlet, but do not use ext cords as a solution to an electrical supply need

Storage in closets and rooms must not be within 18" of the ceiling

Storage closets need smoke detectors

No exit sign on door 113

main door, 120 shop exit, 131a, adlt marine side of shop,

120 shop exit, lights by sop entrance 120,

graphics room, if upsatirs is to be used as a class, emergency lighting is needed up there.

room 136 has 1 old-style extinguisher that needs service/inspection or removal.

Shell area needs 1 additional extinguisher by the shop side of Jack's office.

fire keys do not include keys to foyer display closet or the elevator service room.

137c-

Ag building lab, 2 ext/emergency lights do not work.

storage too close to ceiling, cannot be within 18"

mechanical room

green house

Safety Concerns

Building Action

Ceiling tiles displaced or stained., Water leakage evident.
 Electrical panel is not accessible.
 Extension cords improperly used.
 Extension cords improperly used., Brown by new computer s
 Ceiling tiles displaced or stained.
 Extension cords improperly used.
 Emergency procedures are not posted.
 Em light needs battery
 Emerg lighting needed
 Exit light battery
 Fire extinguisher issue.
 Light bulbs, Extension cords improperly used.
 Ceiling tiles displaced or stained.
 Ceiling tiles displaced or stained., Emerg lighting needed
 Em light needs service
 Electrical panel is not accessible.
 Extension cords improperly used., Exit light battery
 Exit light needs service
 Extension cords improperly used.
 Reposition power strip
 Extension cords improperly used.
 Extension cords improperly used.
 Exit light bulb
 Safety light not working

wILBERT
 Corrected 11August
 email
 EMAIL
 WILBERT
 EMAIL
 Corrected 11August
 WILBERT
 WORKORDER
 WILBERT
 ORDERED
 EMAIL
 WILBERT
 WILBERT/WORKORDER
 WORKORDER
 AUCTION WILL CORREC
 EMAI/ WILBERT
 WORKORDER
 EMAIL
 CORRECTED
 EMAIL
 EMAIL
 WILBERT
 WORKORDER

Emergency procedures are not posted.
 Extension cords improperly used., Multioutlet adapter
 Storage is within 24" of ceiling., No smoke detectors
 Electrical panel is not accessible.
 Electric scent
 Em light needs service
 Remove Christmas lights

Emergency light, battery and is obstructed
 Smoke detectors required
 Multiple Em lights need service
 Exit light battery

Em light needs battery
 Electrical panel is not accessible.
 stored tables in exit hallway.



	<p>Workorder scheduled moved out of room or out of path replaced workorder with technology</p> <p>Email to indiv. on 8/13 Email to indiv. on 8/13</p>
--	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------



<p>Exit sign needs battery or other attention emergency lights need attention</p>	<p>Maint W/O 5346013 Maint W/O 5346013 Maint W/O 5346017 Maint W/O 5346024</p>
---------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------



<p>flammable paint products need to be in a fire closet</p> <p>Blocked access to electrical panel Outlet box is open with exposed wires/ extension cords used as permanant electrical supply</p>	<p>Maint W/O 5346019 Instructor informed Maint W/O 5346016 & 534 Email to Ag Instructors 8/13 Email to Ag Instructors 8/13 Maint W/O 5346018</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------


DRAFT

District Follow up



T

DRAFT



6017
3
3

DRAFT