

SAFETY WALK THROUGH RESULTS

5-Sep-14

an email address if you wish to be updated as to the status of your concern.	For which building is a safety notation being made?	Please state the room number or other description of location.	Please detail the safety concern observed or pick one of choices.	
wkurtz@camdentonschools.org	Middle School	Just outside security door, west side of sidewalk	Hole in the ground by drain	
wkurtz@camdentonschools.org	Middle School	downspout by little theatre	Hole in the ground by drain	
wkurtz@camdentonschools.org	Middle School	bottom level corridor	rubber floor covering loose at bottom of ramp	
wkurtz@camdentonschools.org	Middle School	middle level health hallway	Ceiling tiles displaced or stained.	
wkurtz@camdentonschools.org	Middle School	garage-laquer room	dust collector full	
wkurtz@camdentonschools.org	Middle School	Shop room	water fountain panel is missing	
wkurtz@camdentonschools.org	Hawthorn	library	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	103	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	105	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	119	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	116	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	117	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	113	Emergency procedures are not posted.	
wkurtz@camdentonschools.org	Hawthorn	114	Emergency procedures are not posted.	

wkurtz@camdentonschools.org	Hawthorn		Emergency procedures are not posted.	112
wkurtz@camdentonschools.org	Hawthorn		Emergency procedures are not posted.	111
wkurtz@camdentonschools.org	Hawthorn		Emergency procedures are not posted.	122
wkurtz@camdentonschools.org	Hawthorn		emergency proc stacked on top each other	120
wkurtz@camdentonschools.org	Hawthorn	94A	Storage is within 24" of ceiling.	
wkurtz@camdentonschools.org	Hawthorn	89B	Storage is within 24" of ceiling.	
wkurtz@camdentonschools.org	Hawthorn	99s	Storage is within 24" of ceiling.	
wkurtz@camdentonschools.org	Hawthorn		Storage is within 24" of ceiling.	132
wkurtz@camdentonschools.org	Hawthorn	library	Storage is within 24" of ceiling.	
wkurtz@camdentonschools.org	Hawthorn		Light bulbs, flourescent bulbs only please	129,126,125
wkurtz@camdentonschools.org	Hawthorn	96 S	Storage is within 24" of ceiling.	
wkurtz@camdentonschools.org	Hawthorn	86 A	Electrical panel is not accessible., closet needs cleaning to access panel	
wkurtz@camdentonschools.org	Hawthorn	choir room storage closet	Storage is within 24" of ceiling.	
wkurtz@camdentonschools.org	Hawthorn		Ceiling tiles displaced or stained.	90
wkurtz@camdentonschools.org	Hawthorn	8th grade locker room	Ceiling tiles displaced or stained.	
wkur	Hawthorn		Storage is within 24" of ceiling.	90

wkurtz@camdentonschools.org	Middle School	Level 3 stairwell by elevator	handrail leaves large gap at ground level	
wkurtz@camdentonschools.org	Dogwood	rm 50-hallway	Ceiling tiles displaced or stained.	
wkurtz@camdentonschools.org	Dogwood	playground	security camera is pointing to sky	
wkurtz@camdentonschools.org	Dogwood	playground	broken swing is wrapped around top. Remove or repair.	
wkurtz@camdentonschools.org	Dogwood	Workroom	TV on stand does not appear secure.	
wkurtz@camdentonschools.org	Dogwood	Between flower bed by front door and wall.	Hole in the ground by drain	
wkurtz@camdentonschools.org	Dogwood	Stairs to Dandoys office	Loose handrail.	
wkurtz@camdentonschools.org	Dogwood	Hallway by Wirths door	Water leakage evident., water stain on wall	
wkurtz@camdentonschools.org	Dogwood	29S hallway	Electrical covers loose or exposed wiring.	
wkurtz@camdentonschools.org	Dogwood	hallway by volunteer services	Ceiling tiles displaced or stained.	
wkurtz@camdentonschools.org	Oak Ridge		Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	6-206	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	6-204	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		Emergency procedures are not posted.	9/3/2014

wkurtz@camdentonschools.org	Oak Ridge		202	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		238	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		182	Emergency procedures are not posted., Empty room	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		192	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	Far 6th grade hallway		Ceiling tiles displaced or stained.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		201	Ceiling tiles displaced or stained.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	Custodian closet 5th grade hall		Ceiling tiles displaced or stained.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		177	Ceiling tiles displaced or stained., Teacher states that there is a chronic ac leak	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		104	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		107	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		181	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		241	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		213	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		204	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		203	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		253	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		125	Griddle- check on this	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	closet by 107		Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	6-206		Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	6-215		Storage is within 24" of ceiling.	9/3/2014

wkurtz@camdentonschools.org	Oak Ridge	closet near 207	Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		202 Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		238 Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge	closet by 239	Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		253 Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	Oak Ridge		190 Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	High School	c102	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	c104	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	a100	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	a102	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b100	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b102	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b108	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b110	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b210	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b206	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	b202		9/3/2014

wkurtz@camdentonschools.org	High School	a214	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	c202	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	c212	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	c214	Emergency procedures are not posted.	9/3/2014
wkurtz@camdentonschools.org	High School	d102	Light bulbs	9/3/2014
wkurtz@camdentonschools.org	High School	a104	Storage is within 24" of ceiling.	9/3/2014
wkurtz@camdentonschools.org	High School	hallway by 116	2 unsecured ladders in the hallway	9/3/2014
wkurtz@camdentonschools.org	High School	commons	Wheeled scaffolding unsecured	9/3/2014
wkurtz@camdentonschools.org	High School	a204, a206	1 doorway blocked- check on this	9/3/2014
wkurtz@camdentonschools.org	Middle School	level 3 hall by elevator	Electrical covers loose or exposed wiring.	9/3/2014
wkurtz@camdentonschools.org	LCTC	Stairwell to marine	Light flickers or is out	9/3/2014
wkurtz@camdentonschools.org	LCTC	Stairwell to marine	Concrete steps are cracked and shift within steel frames	9/3/2014
wkurtz@camdentonschools.org	LCTC		This door only locks one way. 109 Needs to lock on both sides	9/3/2014
wkurtz@camdentonschools.org	LCTC	Ag building.	door has no lock	9/3/2014
wkurtz@camdentonschools.org	LCTC	ag building area	old green house pipes are protruding from ground.	9/3/2014
wkurtz@camdentonschools.org	LCTC	Ag area	No handrail on retaining wall steps	9/3/2014

wkurtz@camdentonschools.org	LCTC	boiler room	Water leakage evident.	9/3/2014
wkurtz@camdentonschools.org	LCTC	boiler room	No light at exterior exit	9/3/2014
wkurtz@camdentonschools.org	LCTC	Collision Repair shop	new safety tape for floor	9/3/2014
wkurtz@camdentonschools.org	LCTC	foyer	Water leakage evident., Sky lights leak	9/3/2014
wkurtz@camdentonschools.org	LCTC	Law Enforcement	Ceiling tiles displaced or stained.	9/3/2014
wkurtz@camdentonschools.org	LCTC	109B	Ceiling tiles displaced or stained.	9/3/2014
thadfield@camdentonschools.org	Hurricane Deck	kindergarten classroom	Ceiling tiles displaced or stained., Water leakage evident.	8/27/2014
thadfield@camdentonschools.org	Hurricane Deck	gym, cafeteria,counselors office,art	Emergency procedures are not posted.	8/27/2014
thadfield@camdentonschools.org	Hurricane Deck	office	Emergency procedures are not posted., emergency call list by phones	8/27/2014
thadfield@camdentonschools.org	Osage Beach	Building-wide	Emergency procedures are not posted., emergency procedures need to be standardized	9/4/2014
thadfield@camdentonschools.org	Osage Beach	office	Emergency procedures are not posted., Emergency numbers need to be posted by phones	9/4/2014